

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: COG Operating, LLC (OGRID# 229137)	Contact: Robert McNeill	
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No.: 432-683-7443	
Facility Name: Pan Head Fee #011H	Facility Type: Oil Well	
Surface Owner: Private	Mineral Owner: Private	API No.: 30-025-42817

LOCATION OF RELEASE

Unit Letter D	Section 11	Township 17S	Range 32E	Feet from the 195	North/South Line North	Feet from the 600	East/West Line West	County Lea
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	---------------

Latitude: 32.85579986 Longitude: -103.7437411 NAD83

NATURE OF RELEASE

Type of Release: Oil & Produced Water	Volume of Release: 4bbls Oil & 4bbls PW	Volume Recovered: 3bbls Oil & 3bbls PW
Source of Release: 1/4" valve	Date and Hour of Occurrence: 2/17/2018	Date and Hour of Discovery: 2/17/2018 8:00am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		

APPROVED

By Olivia Yu at 11:00 am, Aug 29, 2018

Describe Cause of Problem and Remedial Action Taken.*

The 1/4" valve leading to the tubing gauge was left open. The valve busted overnight resulting in the release. The valve was replaced.

Describe Area Affected and Cleanup Action Taken.*

All of the fluid remained on location. A vacuum truck was utilized to recover all freestanding fluids. Concho will have the spill area evaluated for any possible impact from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation activities.

Remediation activities were conducted in accordance with an NMOCD-approved Workplan. Please reference the Workplan dated March 16, 2018, and the Remediation Summary and Closure Report dated August 7, 2018, for additional details regarding remediation activities.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Rebecca Haskell</i>		OIL CONSERVATION DIVISION	
Printed Name: Rebecca Haskell		Approved by Environmental Specialist: <i>CGY</i>	
Title: Senior HSE Coordinator	Approval Date: 8/29/2018	Expiration Date: xx/xx/xxxx	
E-mail Address: rhaskell@concho.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: August 13, 2018 Phone: 432-701-8630			

* Attach Additional Sheets If Necessary

1RP-4971