

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

#### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Chevron USA, Inc.	Contact: Amy Barnhill
Address: 6301 Deauville Blvd., Midland, TX 79706	Telephone No.: 432-687-7108
Facility Name: Salado Draw Area	Facility Type: Lease Road
Surface Owner: Federal	Mineral Owner: Private
API No.: Not Applicable; spill occurred on lease road	

#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	29	26S	35E					Lea

Latitude: 32.012119 Longitude: -103.381322 NAD83

#### NATURE OF RELEASE

Type of Release: Spill	Volume of Release: 620 barrels produced/brackish water	Volume Recovered: 260 barrels produced/brackish water
Source of Release: 12" frac flat hose	Date and Hour of Occurrence: 05/26/2017; 06:00 PM	Date and Hour of Discovery: 05/26/2017; 06:00 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Olivia Yu; Maxey Brown - NMOCD Jim Amos - BLM	
By Whom?	Date and Hour: 05/27/2017; 03:20 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		

**APPROVED**

**By Olivia Yu at 11:25 am, Sep 05, 2018**



Describe Cause of Problem and Remedial Action Taken.\*

A tractor trailer ran over above-ground 12" frac flat hose, releasing 620 barrels produced/brackish water on land. Recovered 260 barrels

Describe Area Affected and Cleanup Action Taken.\* Reference 1RP-4715

The spill to land was on disturbed ditch and did not impact vegetation nor flow to any sensitive habitat, or water way. Vacuum truck recovered 260 barrels. Remediation plan was submitted and closure report is attached.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>		
Printed Name: Amy Barnhill	Approved by Environmental Specialist: 		
Title: Waste/Water Specialist	Approval Date: 9/5/2018	Expiration Date: xx/xx/xxxx	
E-mail Address: ABarnhill@chevron.com	Conditions of Approval: Like approval from BLM.		Attached <input type="checkbox"/>
Date: 6-18-18	Phone: 432-687-7108		

\* Attach Additional Sheets If Necessary

1RP-4715