

**From:** [Hernandez, Christina, EMNRD](#)  
**To:** ["Mann, Ryan"; "Joel Lowry"](#)  
**Subject:** RE: 1RP-5082 - Energen State B - Site Assessment Report and Proposed Remediation Plan  
**Date:** Wednesday, January 16, 2019 10:36:00 AM  
**Attachments:** [1RP-5082 - State B - C-141 Pages1-5Signed.pdf](#)  
[image001.png](#)  
[1RP-5082 - State B - Site Assessment Report and Proposed Remediation Plan \(2\).pdf](#)

---

Mr. Lowry:

NMOCD approves of the delineation completed for **1RP-5082**. The proposed remediation and sampling plan are also approved with these conditions:

- Confirmation sampling must include the sidewall at the border between the different depths of excavation for SP1 and SP2 areas.
- Excavated material must be placed on liner pending transport.
- Dated photo documentation of the remedial activities.
- Scaled map with the confirmation sample locations in relation to the delineation sample points.

Thanks,  
Christina Hernandez  
EMNRD-OC  
Environmental Specialist  
1625 N. French Drive  
Hobbs, NM 88240  
575-393-6161 ext. 111  
[Christina.Hernandez@state.nm.us](mailto:Christina.Hernandez@state.nm.us)

---

**From:** Mann, Ryan <[rmann@slo.state.nm.us](mailto:rmann@slo.state.nm.us)>  
**Sent:** Thursday, January 3, 2019 11:18 AM  
**To:** 'Joel Lowry' <[joel@lowryenvironmental.com](mailto:joel@lowryenvironmental.com)>; Hernandez, Christina, EMNRD <[Christina.Hernandez@state.nm.us](mailto:Christina.Hernandez@state.nm.us)>  
**Subject:** [EXT] RE: 1RP-5082 - Energen State B - Site Assessment Report and Proposed Remediation Plan

Good morning Mr. Lowry,

NMSLO approves of the proposed with the following comments:

- Confirmation samples need to be taken on the sidewall of all excavation of differing depths. SP1 and SP2 will most like have differing depth. The North @1' looks like it will be a separate excavation and will not adjoin.

Approval is also necessary from NMOCD.

---

**From:** Joel Lowry [<mailto:joel@lowryenvironmental.com>]  
**Sent:** Wednesday, December 19, 2018 2:35 PM  
**To:** [christina.hernandez@state.nm.us](mailto:christina.hernandez@state.nm.us); Mann, Ryan <[rmann@slo.state.nm.us](mailto:rmann@slo.state.nm.us)>  
**Subject:** 1RP-5082 - Energen State B - Site Assessment Report and Proposed Remediation Plan

Please find attached the *Site Assessment Report and Proposed Remediation Plan* along with pages from the Form C-141, that has been prepared for Energen's State B. The Site is located on State Land in UL "J", Section 1, Township 16 South, Range 35 East in Lea County, New Mexico. Upon your review and approval, Energen is prepared to continue remediation activities as outlined within the attached. If you have any questions or need any additional information, please feel free to contact myself or Tommy York by phone or email. Thanks.

Respectfully,

**Joel Lowry**

Environmental Professional



PO Box 896  
Lovington, NM 88260  
Direct 432-466-4450

*The content of this email may be confidential and/or privileged. If you are not the intended recipient, or an authorized representative of the intended recipient, please notify Lowry Environmental and delete this email from your system at your earliest convenience. Dissemination or copying of this email, its content or its attachments is prohibited.*

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit [https://clicktime.symantec.com/a/1/JSkKHUFnrrgCfGJjBlvHhMFFfVFau8wLqp-lDbRKQn8=?d=Hi27pxkgyhimNQk0g77y2ms5aovY7BjDLdDjSHQf17mPn8x3Dhcu-xcMsnZl7Ln4LFEylq\\_aljh7OvoiFotPP3-PmehniHzHDg8wliwuPbigvv1lcHOHjHfGd4QOBjJdW8r0x8Zuv03h\\_Ntm8cw3z2\\_zk5FSTzQ0il5D75oiSyAjjjJsLj2QTZQ4DT-15TY5IsMWVgI-j35EOgo4O4EzKdplkDsA0TH9MYGBbrVD6VjvDUXe8a6FAWrc8rkGDJeSrg8B4U-sIC-O9dzxf8hvS9EPiQ6-qrRn8Tf1hmH2g\\_O-6lpPHGHt0XiktdNNQUFGGrXzJl22a\\_CD0tt7PcEbTTjgXovvLqWzx1-4foqnmctWU1B-tHEeCVZtIJY6LEKXhPtz8Cx2d\\_seRwoWs6T9G9eaWqT6iMv9-harYAk7wlQVEFTC28tpiLDJoZv3-9HyZw%3D%3D&u=http%3A%2F%2Fwww.symanteccloud.com](https://clicktime.symantec.com/a/1/JSkKHUFnrrgCfGJjBlvHhMFFfVFau8wLqp-lDbRKQn8=?d=Hi27pxkgyhimNQk0g77y2ms5aovY7BjDLdDjSHQf17mPn8x3Dhcu-xcMsnZl7Ln4LFEylq_aljh7OvoiFotPP3-PmehniHzHDg8wliwuPbigvv1lcHOHjHfGd4QOBjJdW8r0x8Zuv03h_Ntm8cw3z2_zk5FSTzQ0il5D75oiSyAjjjJsLj2QTZQ4DT-15TY5IsMWVgI-j35EOgo4O4EzKdplkDsA0TH9MYGBbrVD6VjvDUXe8a6FAWrc8rkGDJeSrg8B4U-sIC-O9dzxf8hvS9EPiQ6-qrRn8Tf1hmH2g_O-6lpPHGHt0XiktdNNQUFGGrXzJl22a_CD0tt7PcEbTTjgXovvLqWzx1-4foqnmctWU1B-tHEeCVZtIJY6LEKXhPtz8Cx2d_seRwoWs6T9G9eaWqT6iMv9-harYAk7wlQVEFTC28tpiLDJoZv3-9HyZw%3D%3D&u=http%3A%2F%2Fwww.symanteccloud.com)

---