

INCLINATION REPORT


FIELD NAME	LEASE NAME Herradura	Well Number 4
OPERATOR Xeric		County Lea
ADDRESS P.O. Box 352 Midland, Texas 79702		
LOCATION (Section, Block, and Survey) J-15-195-38e, 1928/5 & 2161E		

30-025-36051

RECORD OF INCLINATION

Measured Depth (feet)	Course Length (Hundreds of feet)	Angle of Inclination (Degrees)	Displacement per Hundred Feet (Sine of Angle x100)	Course Displacement (feet)	Accumulative Displacement (feet)
302	302	0.75	1.31	3.95	3.95
616	314	1.00	1.75	5.48	9.43
892	276	1.00	1.75	4.82	14.25
1205	313	0.75	1.31	4.10	18.35
1674	469	0.75	1.31	6.14	24.49
1950	276	0.50	0.87	2.41	26.90
2350	400	1.25	2.18	8.73	35.62
2640	290	1.75	3.05	8.86	44.48
2951	311	1.50	2.62	8.14	52.62
3130	179	1.00	1.75	3.12	55.75
3407	277	1.00	1.75	4.83	60.58
3945	538	1.50	2.62	14.08	74.67
4459	514	0.50	0.87	4.49	79.15
4958	499	1.75	3.05	15.24	94.39
5396	438	1.25	2.18	9.56	103.95
5919	523	1.25	2.18	11.41	115.36
6390	471	1.00	1.75	8.22	123.58
6892	502	0.75	1.31	6.57	130.15
7413	521	1.25	2.18	11.37	141.52
7740	327	1.50	2.62	8.56	150.08

Accumulative total displacement of well bore at total depth of 7740 feet = 150.08 feet



Lisa Wilkes-Richardson

Signature of Authorized Representative
Lisa Wilkes-Richardson, Asst. Secretary
Name of Person and Title (type or print)
Star Drilling Corporation
Name of Company
Telephone: (915) 684-5337
Area Code

Signature of Authorized Representative
Name of Person and Title (type or print)
Xeric
Operator
Telephone:
Area Code