

State of New Mexico
 Energy, Minerals and Natural Resources Department
 Oil Conservation Division Hobbs District Office

JUL 13 2014

BRADENHEAD TEST REPORT

RECEIVED

Operator Name Lime Rock Resources II-A, L.P.	API Number 30-025-24176
Property Name North Vacuum ABO North Unit	Well No. #001

7. Surface Location

UL - Lot J	Section I	Township 17S	Range 34E	Feet from 1780	N/S Line South	Feet From 2000	E/W Line East	County Lea
---------------	--------------	-----------------	--------------	-------------------	-------------------	-------------------	------------------	---------------

Well Status

Well Status - A	SHUT-IN	PRODUCING Injection	DATE 04-17-2014
-----------------	---------	------------------------	--------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A) Surf-Interm	(B) Interm(1)-Interm(2)	(C) Interm-Prod	(D) Prod C/sng	(E) Tubing
Pressure	0		5	5	50
<u>Flow Characteristics:</u>					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH X	SALTY	SULFUR	BLACK
-------	---------	-------	--------	-------

Remarks:

Failed MIT. Shut in for repairs.

FOR RECORD ONLY

Tested by Eddie Elliott 432-413-0429

Reported by Trish Mcaland 575-623-8424

*Letter of Violation 7/21/2014
 RAB/OCD.*

BS 7/13/2014

Signature: <i>Trish Mcaland</i>	OIL CONSERVATION DIVISION
Printed name: Trish Mcaland	Entered into RBDMS
Title: Production Analyst	Re-test
E-mail Address: pmcaland@limerockresources.com	
Date: 04-23-2014	Phone: 575-623-8424
	Witness:

JUL 22 2014

h