

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUL 24 2014

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEURON		API Number 30-025-36683	
Property Name VACUUM GRAYBURG SAN ANDRES UNIT		Well No. 132	

Surface Location									
UL - Lot 1	Section 2	Township 18S	Range 34E	☒	Feet from 2630	N/S Line FSL	Feet from 660	E/W Line FEL	County LEA

Well Status								
TA'D WELL YES	NO	SHUT-IN YES	NO	INJECTOR INJ ☒	SWD	PRODUCER OIL	GAS	DATE 5/5/14

OBSERVED DATA


	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	0			10	1675
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ☐
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ☒
Surges	Y / N	Y / N	Y / N	Y / N	GAS ☐
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

①) packer fluid bled down to zero

FOR RECORD ONLY

BA 7/25/2014

Signature: 		OIL CONSERVATION DIVISION	
Printed name: Dane McCuen		Entered into RBDMS	
Title: Sub Surface Production Specialist		Re-test	
E-mail Address: lnnb@chevron.com			
Date: 7/18/14	Phone: 575 942-3526		
Witness:			

JUL 30 2014