

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUL 24 2014

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEURON						API Number 30-025-35563			
Property Name VACUUM GRAYBURG SAN ANDRES UNIT						Well No. 249 -			
1. Surface Location									
UL - Lot F	Section 1	Township 18S	Range 34E	☒	Feet from 1390	N/S Line FNL	Feet From 2530	E/W Line FWL	County LEA
Well Status									
TA'D WELL YES		SHUT-IN NO		INJECTOR INJ ☒ SWD		PRODUCER OIL		GAS	
DATE 5/5/14									

OBSERVED DATA


	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	0		1600	1900
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ☐
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ☒
Surges	Y / N	Y / N	Y / N	Y / N	GAS ☐
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

FOR RECORD ONLY

> BHT Failure 1600# on casing
 Mit Violation Letter 7/30/2014 LAD/OCD.
 (called Mr. Britton 7/30/14)

BS 7/25/2014

Signature: 		OIL CONSERVATION DIVISION	
Printed name: Dane McCuen		Entered into RBDMS	
Title: Sub Surface Production Specialist		Re-test	
E-mail Address: lnnb@chevron.com			
Date:	Phone: 575 942-3526		
Witness:			

JUL 31 2014

