

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUL 31 2014

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEURON	*API Number 30-025-36500
Property Name VACUUM GRAYBURG SAN ANDRES UNIT	Well No. 110

2 Surface Location

UL - Lot M	Section 1	Township 18S	Range 34E	☒	Feet from 653	N/S Line FSL	Feet From 20	E/W Line FWL	County LEA
----------------------	---------------------	------------------------	---------------------	-------------------------------------	-------------------------	------------------------	------------------------	------------------------	----------------------

Well Status

TA'D WELL YES	NO	SHUT-IN YES	NO	INJ	INJECTOR SWD	PRODUCER (OIL)	GAS	DATE 5/5/14
------------------	----	----------------	----	-----	-----------------	--------------------------	-----	-----------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0			30	150
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ___
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ___
Surges	Y / N	Y / N	Y / N	Y / N	GAS ___
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

FOR RECORD ONLY

B8 8/11/2014

Signature: [Signature]	OIL CONSERVATION DIVISION
Printed name: Dane McCuen	Entered into RBDMS
Title: Sub Surface Production Specialist	Re-test
E-mail Address: lennb@chevron.com	
Date: 7/23/14	Phone: 575 942-3526
Witness:	

AUG 13 2014

[Signature]