

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUL 25 2014

BRADENHEAD TEST REPORT

RECEIVED

Operator Name CHEURON		API Number 30-025-31871	
Property Name VACUUM GLORIETTA WEST UNIT		Well No. 63	

Surface Location

UL - Lot H	Section 35	Township 17S	Range 34E	☒	Feet from 1340	N/S Line FNL	Feet From 1090	E/W Line FEL	County LEA
----------------------	----------------------	------------------------	---------------------	-------------------------------------	--------------------------	------------------------	--------------------------	------------------------	----------------------

Well Status

TA'D WELL YES	NO	SHUT-IN ☒ YES	NO	INJECTOR ☒ INJ	SWD	PRODUCER OIL	GAS	DATE 5-2-14
------------------	----	---	----	--	-----	-----------------	-----	-----------------------


OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0			0	25
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ☐
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ☒
Surges	Y / N	Y / N	Y / N	Y / N	GAS ☐
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid Injected for Waterflood if applies
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Currently down for Rig work.
FOR RECORD ONLY

BS 8/08/2014

Signature: 		OIL CONSERVATION DIVISION	
Printed name: Dane McCuen		Entered into RBDMS	
Title: Sub Surface Production Specialist		Re-test	
E-mail Address: lmb@chevron.com			
Date: 7/14/14	Phone: 575-942-3526		
Witness:			

AUG 18 2014

