

State of New Mexico
 Energy, Minerals and Natural Resources Department
 Oil Conservation Division Hobbs District Office

JUL 25 2014

BRADENHEAD TEST REPORT

RECEIVED

Operator Name CHEURON		API Number 30-025-31815
Property Name VACUUM GLORIETTA WEST UNIT		Well No. 42

Surface Location

U/L - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
M	30	17S	35E	1114	FSL	41	FWL	LEA

Well Status

TA'D WELL	SHUT-IN	INJECTOR	PRODUCER	DATE
YES	NO	YES	NO	
		IN	SWD	5-5-14

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod C'ng	(E)Tubing
Pressure	0			205	0
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR
Surges	Y / N	Y / N	Y / N	Y / N	GAS
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

(D) oil bleed down to zero, 24 hours later had 40 lbs back on production string. **Failure**.

FOR RECORD ONLY

Operation Succeeded
 Well failed. bti.

Letter of Violation 8/19/2014
 SJS/OCD BS 8/1/2014

Signature:	OIL CONSERVATION DIVISION
Printed name: Dane McCuen	Entered into RBDMS
Title: Sub Surface Production Specialist	Re-test
E-mail Address: lmb@chevron.com	
Date: 7/14/14	Phone: 575-942-3526
Witness:	

AUG 20 2014

h