

State of New Mexico Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION

1220 South St. Francis Dr. Santa Fe, NM 87505

District I 1625 N. French Dr., Hobbs, NM 88240
District II 1301 W. Grand Ave., Artesia, NM 88210
District III 1000 Rio Brazos Rd. Aztec, NM 87410
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

WELL API NO.

30-025-28447

5. Indicate Type of Lease STATE [X] FEE [ ]

6. State Oil & Gas Lease No. AO-2614

7. Lease Name or Unit Agreement Name South Eunice Seven Rivers Qn Unit

8. Well Number 434

9. OGRID Number 873

10. Pool Name Eunice; Seven Rivers/Qn, South

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR DEEPE...)

1. Type of Well: Oil Well [X] Gas Well [ ] Other [ ]

2. Name of Operator Apache Corporation

3. Address of Operator 303 Veterans Airpark Ln., Ste. 3000, Midland, TX, 79705

4. Well Location Unit Letter D Section 25 Township 1310 Range 22S N 36E W Lea 1280 feet from the line NMPM County

11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3458' GR

12. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK [ ] PLUG AND ABANDON [ ] CHANGE PLANS [ ] MULTIPLE COMPL [ ]
SUBSEQUENT REPORT OF: REMEDIAL WORK [ ] ALTERING CASING [ ] COMMENCE DRILLING OPNS. [ ] P AND A [X] CASING/CEMENT JOB [ ]
OTHER: [ ] [X] Location is ready for OCD inspection after P&A

- [X] All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.
[X] Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.
[X] A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the

OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER / QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. ALL INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.

- [X] The location has been leveled as nearly as possible to the original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.
[X] Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.
[X] If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from the lease and well location.
[X] All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)
[X] All other environmental concerns have been addressed as per OCD rules.
[X] Pipelines and flow lines have been abandoned in accordance with 19.15.9.714.B(4)(b) NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.

When all work has been completed, return this form to the appropriate District office to schedule an inspection. If more than one inspection has to be made to a P&A location because it does not meet the criteria above, a penalty may be assessed.

SIGNATURE [Signature] TITLE P&A Tech DATE 9/22/14

TYPE OR PRINT NAME Leon Sellers leon.sellers@apachecorp.com PHONE: 432-208-0349

APPROVED BY: [Signature] TITLE Compliance Officer DATE 9/29/14

Conditions of Approval (if any):

SEP 30 2014