

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

OCT 21 2014

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEVRON	API Number 300-25-41296
Property Name State AN	Well No. 15

Surface Location

UL - Lot G	Section 7	Township 18s	Range 35E	Feet from 1670	N/S Line N	Feet From 1650	FAW Line E	County Lea
---------------	--------------	-----------------	--------------	-------------------	---------------	-------------------	---------------	---------------

Well Status

Well Status	SHUT-IN	PRODUCING X	DATE 10-8-14
-------------	---------	----------------	-----------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csgg	(E)Tubing
Pressure	0			30	350
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:


CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

INJECTING AT THIS TIME ___ WTR, ___ GAS, ___ CO2

FOR RECORD ONLY

BS 10/24/2014

Signature: 	OIL CONSERVATION DIVISION
Printed name: Daniel Rice	Entered into RBDMS
Title: FSA	Re-test
E-mail Address: DQKB@chevron.com	
Date:	Phone: 575-704-2365
Witness:	

h