

NOV 19 2014

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEVRON	API Number 300 25 25813
Property Name Central Vacuum Unit	Well No. 25

7. Surface Location

U1. - Lot K	Section 25	Township 17S	Range 34E	Feet from 1330	N/S Line S	Feet from 1504	E/W Line W	County Log
----------------	---------------	-----------------	--------------	-------------------	---------------	-------------------	---------------	---------------

Well Status

Well Status	SHUT-IN X	PRODUCING	DATE 11 NOV 2014
-------------	--------------	-----------	---------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA


If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csg	(E)Tubing
Pressure	0		0	335	
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	8 / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	8 / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:	INJECTING AT THIS TIME	WTR	GAS	CO2
D. Bkd to 0				
NOT on file F/Relaps				
Well was Hard shut in after last Bradenhead was completed.				
It was called a failure poll Request has been submitted.				
BS 12/10/2014				

Signature: 	OIL CONSERVATION DIVISION
Printed name: Daniel Pace	Entered into RBDMS
Title: FSA	Re-test
E-mail Address: DQKB@chevron.com	
Date: 11-9-14	Phone: (575) 704 - 2365
Witness:	

FOR RECORD ONLY

DEC 17 2014