

HOBBSOCD

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

DEC 26 2014

BRADENHEAD TEST REPORT

RECEIVED

Operator Name <i>Midland Operating</i>		API Number <i>30-025-11331</i>	
Property Name <i>Langlie Matrik Woodworth</i>		Well No. <i>113</i>	

Surface Location

UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
	<i>33</i>	<i>24S</i>	<i>37E</i>					<i>Lea</i>

Well Status

TA'D WELL ☒ YES ☐ NO	SHUT-IN ☒ YES ☐ NO	INJECTOR ☒ INJ ☐ SWD	PRODUCER ☐ OIL ☐ GAS	DATE <i>11/3/2014</i>
--	--	--	---	--------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	ϕ	ϕ	<i>N/A</i>	ϕ	ϕ
Flow Characteristics					
Puff	Y / ☒ N	Y / ☒ N	Y / ☒ N	Y / ☒ N	CO2 ☐
Steady Flow	Y / ☒ N	Y / ☒ N	Y / ☒ N	Y / ☒ N	WTR ☐
Surges	Y / ☒ N	Y / ☒ N	Y / ☒ N	Y / ☒ N	GAS ☐
Down to nothing	Y / ☒ N	Y / ☒ N	Y / ☒ N	Y / ☒ N	Type of Fluid
Gas or Oil	Y / ☒ N	Y / ☒ N	Y / ☒ N	Y / ☒ N	Injected for
Water	Y / ☒ N	Y / ☒ N	Y / ☒ N	Y / ☒ N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

FOR RECORD ONLY

LAH/OCD

Signature:		OIL CONSERVATION DIVISION	
Printed name:		Entered into RBDMS	
Title:		Re-test	
E-mail Address:			
Date: <i>11/3/2014</i>	Phone:		
Witness: <i>[Signature]</i>			

JAN 07 2015

h -