

MAY 15 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Apache Corp	API Number 30-025-05752
Property Name NMGSAU	Well No. 1013

7. Surface Location

UL - Lot M	Section 30	Township 19S	Range 31E	Feet from 330	N/S Line S	Feet from 330	E/W Line W	County Lea
----------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

TA'D WELL YES	NO	SHUT-IN YES	NO	INJECTOR (INJ)	SWD	PRODUCER OIL	GAS	DATE 4-29-15
------------------	----	----------------	----	--------------------------	-----	-----------------	-----	------------------------

OBSERVED DATA

	(A)Surface	(B)Intern(1)	(C)Intern(2)	(D)Prod Csg	(E)Tubing
Pressure	0	0	0	660	660
<u>Flow Characteristics</u>					
Puff	Y / N	(Y) N	(Y) / N	Y / N	CO2 ☐
Steady Flow	Y / N	Y / N	Y / N	(Y) / N	WTR ☒
Surges	Y / N	Y / N	Y / N	Y / N	GAS ☐
Down to nothing	Y / N	(Y) N	(Y) / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	(Y) / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflow if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

(D) would not stop flowing so I shut in and checked later. The casing was on a vacuum. Left the well shut in until we can work on it. See attached C-103 form

Failed 5/22/2015

Signature: Jim Ellison	OIL CONSERVATION DIVISION
Printed name: Jim Ellison	Entered into RBDMS
Title: Instrument Tech	Re-test
E-mail Address: J.D.Ellison @ apache corp. com	
Date:	Phone: 575-441-7734
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

JUN 02 2015