

JUN 19 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Chevron	API Number 30-025-02227
Property Name UGSAU	Well No. UGSAU 64

Surface Location									
GL - Lot M	Section 35	Township 17S	Range 34E		Feet from 6660	N/S Line 10 S	Feet from 6660	E/W Line W	County LEA

Well Status									
YES	TVD WELL N	YES	SHUT-IN N	INJ	INJECTOR	SWD	OIL	PRODUCER	DATE 5-27-15

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	20	NA	NA	10	180
Flow Characteristics					
Pull	Y / X	Y / N	Y / N	Y / X	CO2 ____
Steady Flow	Y / N	Y / N	Y / N	Y / X	WTR ____
Surges	Y / X	Y / N	Y / N	Y / X	GAS ____
Down to nothing	Y / X	Y / N	Y / N	Y / X	Type of fluid injected for Waterflood if applies
Gas or Oil	Y / X	Y / N	Y / N	Y / X	
Water	Y / X	Y / N	Y / N	Y / X	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Bleeds Down some but has a low pressure steady flow.

B8 6/30/2015

Signature: A. 2. P.	OIL CONSERVATION DIVISION
Printed name: Austin Pogue	Entered into RBDMS
Title: PSA	Re-test
Email Address: etym@chevron.com	
Date: 5-27-15	Phone: 575-513-0363

JUL 15 2015