

JUL 10 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

RECEIVED

Operator Name Cherron	API Number 30-025-31878 ✓
Property Name Vacuum Colarieta West Unit	Well No. 123 ✓

1. Surface Location

W. - Lot C	Section 6	Township 18S	Range 35E	Feet from 1265	N/S Line N	Feet From 2035	E/W Line W	County LEA ✓
----------------------	---------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	------------------------

Well Status

YES	TA'D WELL NO	YES	SHUT-IN NO	INJECTOR NO	SWD	OIL	PRODUCER GAS	DATE 5/7/15
-----	------------------------	-----	----------------------	-----------------------	-----	-----	------------------------	-----------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	N/A	N/A	0	1450
Flow Characteristics					
✓ Pull	Y/N	Y/N	Y/N	Y/N	CO2 —
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR X
Surges	Y/N	Y/N	Y/N	Y/N	GAS —
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if applies

Remarks — Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BS 7/14/2015

Signature: 	OIL CONSERVATION DIVISION
Printed name: Tanner Dutton Chevron	Entered into RBDMS
Title: FSA	Re-test
E-mail Address: T211@chevron.com	
Date: 5/7/15	
Phone: 	
Witness: 	

INSTRUCTIONS ON BACK OF THIS FORM

JUL 22 2015