

JUL 27 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEVRON	Well Number 30-025-30139
Property Name ABO REEF NEW MEXICO AB State	Well Name AB-9

Surface Location

Section P	Range 6	Block 18	Sub-Block S	Section 35	Range E	Block 538	Sub-Block S	Section 818	Range E	Block LEA
---------------------	-------------------	--------------------	-----------------------	----------------------	-------------------	---------------------	-----------------------	-----------------------	-------------------	---------------------

Well Status

YES	NO	YES	NO	YES	NO	YES	NO	YES	NO	DATE 5/27/15

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	0	0	40	300
Flow Characteristics					
Pull	Y / 0	Y / 0	Y / 0	Y / 0	CO2 —
Steady Flow	Y / 0	Y / 0	Y / 0	Y / 0	WTR —
Surges	Y / 0	Y / 0	Y / 0	Y / 0	GAS —
Down to nothing	Y / 0	Y / 0	Y / 0	Y / 0	Type of Fluid
Gas or Oil	Y / 0	Y / 0	Y / 0	Y / 0	Injected loc
Water	Y / 0	Y / 0	Y / 0	Y / 0	Waterhead if applies

Remarks – Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

B& 7/29/2015

Signature:	OIL CONSERVATION DIVISION
Printed name: Ruben Rodriguez	Entered into RBDMS
Title: FSA	Re-test
E-mail Address: TZCL@chevron.com	
Date: 5-27-15	Phone: 505-513-5520

JUL 31 2015