

JUL 27 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Chevron	API Number 30-025-31991 -
Property Name NM AB ST 10	Well No. 10 -

⁷ Surface Location

L.L. - Lat	Section	Township	Range		Feet from	N/S Line	Feet From	E/W Line	County
J	6	18S	35E		2085	S	1872	26	Lea

Well Status


YES ☒ NO ☐	YES ☒ NO ☐	INJ ☐ SWD ☐	OIL ☒ GAS ☐	DATE 5/8/15
---	---	---	--	----------------

OBSERVED DATA

	(A) Surface	(B) Intern(1)	(C) Intern(2)	(D) Prod Casing	(E) Tubing
Pressure	Ø	N/A	N/A	-	Ø
Flow Characteristics					
Pull	Y / Ø	Y / N	Y / N	Y / N	CO2 —
Steady Flow	Y / Ø	Y / N	Y / N	Y / N	WTR —
Surges	Y / N	Y / N	Y / N	Y / N	GAS —
Down to nothing	Ø / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / Ø	Y / N	Y / N	Y / N	Injected for
Water	Y / Ø	Y / N	Y / N	Y / N	Water and if
					applies.

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BS 7/29/2005-

Signature: 		OIL CONSERVATION DIVISION
Printed name: Ruben Rodriguez		Entered into RBDMS
Title: FSA		Re-test
E-mail Address: TZCL@chevron.com		
Date: 5/8/15	Phone: 575-513-5526	
Witness: 		

INSTRUCTIONS ON BACK OF THIS FORM

JUL 31 2015