

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD

JUL 27 2015

BRADENHEAD TEST REPORT

RECEIVED

Operator Name CHEVRON USA, Inc.		Well No. 30-025-31992
Property Name DRENNARD NM L STATE		Well Name L-12

Surface Location

H	1	185	34E	1880	N	660	E	LEA
---	---	-----	-----	------	---	-----	---	-----

Well Status


YES	NO	YES	NO	INJ	SWD	PRODUCER	GAS	DATE
	0		0			0		5/22/15


OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	0	N/A	N/A	35	30
Flow Characteristics					
Pull	0 N	Y / N	Y / N	Y / N	CO2
Steady Flow	Y / 0	Y / N	Y / N	Y / N	WTR
Surges	Y / 0	Y / N	Y / N	Y / N	GAS
Down to nothing	0 / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / 0	Y / N	Y / N	Y / N	Injected for
Water	Y / 0	Y / N	Y / N	Y / N	Water flood if applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

B8 7/29/2015

Signature: 	OIL CONSERVATION DIVISION
Printed name: Mecaz Phears	Entered into RBDMS
Title: FS	Re-test
E-mail Address: OGLME@nmdnr.com	
Date: 5/22/15	Phone: 505-631-8504



JUL 31 2015

