

JUL 27 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENTHEAD TEST REPORT

Operator Name Chevron	U S A Inc.	Well No. 30-025-32007
Property Name DRENKARD	N.M. '2' STATE	Acq. No. 6-13

Surface Location

Section G	Line 1	Corner 185	Angle 34E	Feet from 1780	N/S Line -N	Feet from 1980	E/W Line E	County LEA
---------------------	------------------	----------------------	---------------------	--------------------------	-----------------------	--------------------------	----------------------	----------------------

Well Status


PROD WFL YES	NO	SHUT-IN NO	NO	INJECTOR NO	SWP NO	PRODUCER YES	GAS YES	DATE 5/22/15
------------------------	----	----------------------	----	-----------------------	------------------	------------------------	-------------------	------------------------


OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	0	N/A	N/A	35	70
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2 —
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR —
Surges	Y/N	Y/N	Y/N	Y/N	GAS —
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid Injected for Waterflood if applies
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks – Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BB 7/29/2015-

Signature: 	OIL CONSERVATION DIVISION
Printed name: McCAE PHELPS	Entered into RBDMS
Title: FS	Re-test
E-mail Address: DGLH@Chevron	
Date: 5/22/15	Phone: 575-637-8504



JUL 31 2015

