

State of New Mexico
 Energy, Minerals and Natural Resources Department
 Oil Conservation Division Hobbs District Office

HOBBS OCD
FEB 25 2016
RECEIVED

BRADENHEAD TEST REPORT

Operator Name ✓ Chevron USA	API Number 30-025-41296
Property Name State AN	Well No. 15

Surface Location									
UL - Lot ✓ G	Section 7	Township 18 S	Range 35 E	Feet from 1670	N/S Line N	Feet From 1650	E/W Line E	County Lea	

Well Status									
TA'D WELL ✓ YES	NO	SHUT-IN NO	INJ NO	INJECTOR NO	SWD NO	OIL	PRODUCER OIL	GAS NO	DATE 2/24/16

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csng	(E)Tubing
Pressure	\emptyset			50	200
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 ___
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ___
Surges	Y/N	Y/N	Y/N	Y/N	GAS ___
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if
					applies.

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: P. Dakurah	BS 2/25/16
Printed name: Peter Dakurah	OIL CONSERVATION DIVISION
Title: Field Specialist	Entered into RBDMS CF
E-mail Address: pdak@chevron.com	Re-test
Date: 2-24-2016	Phone: 575-390-7024
Witness: Carol Flowers	

FEB 26 2016

In
C.F.