

APR 12 2016

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Apache Corp.	API Number 30-025-05672
Property Name NMGSAU	Well No. 713 13

Surface Location									
UL - Lot M	Section 21	Township 19S	Range 37E	Feet from 660	N/S Line S	Feet from 660	E/W Line W	County Lea	

Well Status									
TA'D WELL YES	NO	SHUT-IN YES	NO	INJECTOR NO	SWD NO	PRODUCER OIL	GAS NO	DATE 3-29-16	

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	0	N/A	0	685
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 —
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ✓
Surges	Y/N	Y/N	Y/N	Y/N	GAS —
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if
					applies.

Remarks – Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>[Signature]</i>	OIL CONSERVATION DIVISION
Printed name: Jim Ellison	Entered into RBDMS ab
Title: Instrument Tech	Re-test
E-mail Address: J.D.Ellison @ apache Corp.com	
Date: 3-29-16	Phone: 575-41-7734
Witness: Carol Flowers	

BS 5-12-16

[Signature]
MAY 12 2016