

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

HOBBS OOD
14
662

AUG 12 2016

RECEIVED

Operator Name APACHE CORP	API Number 30 025 06350
Property Name NEDU	Well No. 221

7. Surface Location

UL - Lot 0	Section 2	Township 21S	Range 37E	Feet from 2983	N/S Line S	Feet From 2317	E/W Line E	County LEA
----------------------	---------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TAB WELL YES	SHUT-IN NO	INJECTOR INJ	SWD	OIL	PRODUCER	GAS	DATE 1-16-16
------------------------	----------------------	------------------------	-----	-----	----------	-----	------------------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Casing	(E) Tubing
Pressure	2			2	1100
Flow					
Surge	Y/N	Y/N	Y/N	Y/N	CO2
Down to nothing	Y/N	Y/N	Y/N	Y/N	WTR
Gas or Oil	Y/N	Y/N	Y/N	Y/N	GAS
Water	Y/N	Y/N	Y/N	Y/N	Type of Fluid Injected for Waterflood if applicable

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

K.H.
Witness

Signature: DC	OIL CONSERVATION DIVISION
Printed name: DAVID CUMMINGS	Entered into RBDMS
Title: SR PUMPER	Re-test Jan
E-mail Address:	
Date:	
Phone:	
Witness:	