

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

AUG 24 2016

BRADENHEAD TEST REPORT

RECEIVED

Operator Name APACHE CORP	API Number 30 025 06356
Property Name NEDU	Well No. 222

7. Surface Location

UL - Lot I	Section 2	Township 21S	Range 31E	Feet from 3534	N/S Line N	Feet From 990	E/W Line E	County LEA
----------------------	---------------------	------------------------	---------------------	--------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

TA'D WELL YES	SHUT-IN NO	INJECTOR NO	PRODUCER YES	DATE 8-15-16
-------------------------	----------------------	-----------------------	------------------------	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	0		0	1115
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 —
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR —
Surges	Y / N	Y / N	Y / N	Y / N	GAS —
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies.

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: AC	OIL CONSERVATION DIVISION
Printed name: DAVID CUMMINGS	Entered into RBDMS
Title: SR PUMPER	Re-test MA
E-mail Address:	
Date:	
Phone:	
Witness:	