

HOBBS OCD

OCT 04 2016

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name APACHE CORP		API Number 30 025 86728	
Property Name NEDU		Well No. 808	

Surface Location

UL - Lot A	Section 22	Township 21S	Range 37E	Feet from 660	N/S Line N	Feet From 660	E/W Line E	County LEA
----------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

YES	TA'D WELL ☒	NO	YES	SHUT-IN ☒	NO	INJECTOR ☒	SWD	OIL	PRODUCER	GAS	DATE 8-15-16
-----	---	----	-----	---	----	--	-----	-----	----------	-----	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	0		0	450
Flow Characteristics					
Puff	(Y) (X)	(Y) N	Y / N	Y / (N)	CO2 —
Steady Flow	Y / (N)	Y / (N)	Y / N	(Y) N	WTR —
Surges	Y / (N)	Y / (N)	Y / N	Y / (N)	GAS —
Down to nothing	(Y) N	(Y) / N	Y / N	(Y) / N	Type of Fluid
Gas or Oil	Y / (N)	Y / (N)	Y / N	(Y) N	Injected for
Water	Y / (N)	Y / N	Y / N	(Y) (X)	Waterflood if
					applies.

Remarks -- Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

COMM BLEED TO 0 IN 10 MIN. TBG BLEED DOWN
PRES UP 450#
SHUT IN SI

Failure
Letter sent

Signature: DAVID CUMMINGS		OIL CONSERVATION DIVISION	
Printed name: DAVID CUMMINGS		Entered into RBDMS	
Title: SR PUMPER		Re-test	
E-mail Address:			
Date:	Phone:		
	Witness:		