Submit One Copy To Appropriate District Office	State of New Mexico		Form C-103	
District I	Energy, Minerals and Natural Resources		Revised November 3, 2011 WELL API NO.	
1625 N. French Dr., Hobbs, NM 88240 District II	tries II		30-025-10935	/
811 S. First St., Artesia, NM 88210	rst St., Artesia, NM 88210 OIL CONSERVATION DIVISION		5. Indicate Type of Lease	
District III 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410		STATE FEE	/	
District IV Santa Fe, NM 8/505		6. State Oil & Gas Lease No.		
1220 S. St. Francis Dr., Santa Fe, NM 87505				
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name or Unit Agreement Name MYERS LANGLIE MATTIX UNIT	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		8. Well Number		
I. Type of Well: Oil Well Gas Well Other INJECTION		115	V	
2. Name of Operator OXY USA WTP LP FEB 2 3 2017		9. OGRID Number 192463	/	
3. Address of Operator		10. Pool name or Wildcat		
PO BOX 4294; HOUSTON, TX 77	RECEIVED	/ED	LANGLIE MATTIX 7RVR QN-GB	
4. Well Location	NL CL	VLU		
Unit Letter O: 660 feet from the SOUTH line and 1980 feet from the EAST line				
Section 33 Township 23S Range 37E NMPM County LEA				
11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
3286				
12. Check Appropriate Box to	Indicate Nature of Notice, Re	eport or Other D	ata	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
NOTICE OF INTENTION TO: SUB PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WOR				
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR				
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT		_
_			_	1 tra
OTHER:				
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.				
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the				
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR				
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.				
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and				
other production equipment.				
 Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with 				
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and funk have been removed				
from lease and well location.				
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have				
to be removed.) All other environmental concerns have been addressed as per OCD rules.				
All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-				
retrieved flow lines and pipelines.				
If this is a one-well lease or last remaining well on lease; all electrical service poles and lines have been removed from lease and well				
location, except for utility's distributi	on infrastructure.			
When all work has been completed, return this form to the appropriate District office to schedule an inspection.				
			7-72-1	7
SIGNATURE W	TITLE_E	ENVIRONMENTA	LADVISOR_DATE 2-23-	{{
TYPE OR PRINT NAME _CASEY L SUMMERS E-MAIL: _casey_summers@oxy.com PHONE: _575-513-8289				
For State Use Only				
Y\1 . 0 ()	111	DEC	DATE 02/2	2/201
APPROVED BY: Mal Whiteh TITLE P.E.S. DATE 02/23/2017 Conditions of Approval (if any):				
Conditions of Approval (II ally).				

Summers, Casey L

From:

Reynolds, Michelle M

Sent:

Wednesday, January 25, 2017 12:48 PM

To:

Chase Lawrence (chase.lawrence@energytransfer.com)

Cc:

Summers, Casey L

Subject:

MLMU 115 Meter Run Removal Notice

Attachments:

IMG_3389.PNG; IMG_3390JPG

Chase,

Oxy's MLMU 115 well has been P&A and therefore we request Energy Transfer remove the old meter run. The location coordinates are 32.2553636, -103.1657028.

A photo of the site is also attached.

Thank you,

Michelle Reynolds

Commercial Gas Operations Specialist

Oxy Midstream Strategic Development LLC | 5 Greenway Plaza, Suite 110 | Office 16.081 | Houston, Texas 77046-0521 Office: (713) 497-2010 | Mobile: (281) 727-9531