## State of New Mexico Energy, Minerals and Natural Resources Department MAR 2 9 2017

**BRADENHEAD TEST REPORT** 

HOBBS OCD

		BRADENI	HEAD TES	T REPORT	P	Ea-	**	
Operator Name Cross Timber Energy, LLC						3002529387		
Property Name						Well No.		
North Vacuum ABO East Unit						16		
		<sup>7.</sup> Su	rface Location	1				
O Section 7	Township Range 17S 35E		Feet from 660		Feet From 1800	E/W Line FEL	County Lea	
		V	Vell Status					
Well Status  ACTIVE  SHUT-IN			PRODUCING		3-8.2017			
•	BRADENHEAD AND IN	TERMEDIATE TO	O ATMOSPHER					
If bradenhead flowed wate	er, check all of the descrip	OBSE	ERVED DA	TA				
	(A)Surf-Interm		(B)Interm(1)-Interm(2)		od (I	)Prod Csng	(E)Tubing	
Pressure	0 ps1	0 051				ZS psi	30 psi	
Flow Characteristics						/		
Puff	Y / 🕥	Y /	Y / N			YIW	1	
Steady Flow	Y / 🔊	Y /	N	Y / N		YIN		
Surges	Y / 10	Y /	N	Y / N		YIN		
Down to nothing	Ø N	Y / N		Y / N		ý/N		
Gas or Oil	Y / 👏	Y /	Y / N			YIN		
Water	Y / X)	Y / N		Y / N		YIN		
If bradenhead flowed water	er, check all of the descrip	tions that apply:						
CLEAR	CAR FRESH		ſΥ	SULFUR		BLACK		
Remarks:			1	INJECTING AT	THIS TIME	WTR,(	GAS,CO2	
Signature: Ana Ana					OIL CONSERVATION DIVISION			
Printed name: Tase Casas					Entered into RBDMS			
Title: /ease Operator					Re-test Re-test			
		SVES . LOM				1.4		
Date: 3-8-2017		75-746-	7220					
	Witness							