

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name CHEVRON MIDCONTINENT, L.P.	³ API Number 30025-3775
Property Name LOVINGTON PADDOCK UNIT	Well No. 31

⁷ Surface Location

UL - Lot L	Section 30	Township 10S	Range 30E	Feet from 1050	N/S Line S	Feet From 890	E/W Line W	County LEA
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

Well Status ACTIVE	SHUT-IN	PRODUCING INT	DATE 3-14-18
------------------------------	---------	-------------------------	------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA



If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csg	(E)Tubing
Pressure	0	0	N/A	0	2100
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	
Steady Flow	Y/N	Y/N	Y/N	Y/N	
Surges	Y/N	Y/N	Y/N	Y/N	
Down to nothing	Y/N	Y/N	Y/N	Y/N	
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:	INJECTING AT THIS TIME ___ WTR, ___ GAS, ___ CO2
----------	--

Signature: 	OIL CONSERVATION DIVISION
Printed name: MARY K. JOHNSON	Entered into RBDMS
Title: FSA	Re-test 
E-mail Address: mkj01@chevron.com	
Date: 3-14-18	
Phone: 432, 955, 8467	
Witness: Gary Robinson	