

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name CHEVRON MIDCONTINENT, L.P.	³ API Number 30025 03831
Property Name LOVINGTON PADDOCK UNIT	Well No. 60

⁷ Surface Location

UL - Lot F	Section 1	Township 17S	Range 30E	Feet from 1980	N/S Line n	Feet From 2310	E/W Line w	County LEA
----------------------	---------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

Well Status ACTIVE	SHUT-IN	PRODUCING INT	DATE 3-13-18
------------------------------	---------	-------------------------	------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA



If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Casing	(E)Tubing
Pressure	0	N/A	N/A	0	1400
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	
Steady Flow	Y/N	Y/N	Y/N	Y/N	
Surges	Y/N	Y/N	Y/N	Y/N	
Down to nothing	Y/N	Y/N	Y/N	Y/N	
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks: INJECTING AT THIS TIME ___ WTR, ___ GAS, ___ CO2

Signature: 	OIL CONSERVATION DIVISION
Printed name: Martin Rodriguez	Entered into RBDMS
Title: PSA	Re-test 
E-mail Address: MRBFC@chevron.com	
Date: 3-13-18	
Phone: 432 955 8462	
Witness: Davey Robinson	