

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

HOBBS OCD
APR 03 2018
RECEIVED

Operator Name CHEVRON MIDCONTINENT, L.P.	³ API Number 3002503811
Property Name LOVINGTON SAN ANDRES UNIT	Well No. 41

7. Surface Location

UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
G	1	17S	36E	1980	N	1980	E	LEA

Well Status

Well Status ACTIVE	SHUT-IN	PRODUCING INT	DATE 3-13-18
------------------------------	---------	-------------------------	------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA



If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csg	(E)Tubing
Pressure	0	0	N/A	0	1350
<u>Flow Characteristics</u>					
Puff	Y/ N	Y/ N	Y/N	Y/ N	
Steady Flow	Y/ N	Y/ N	Y/N	Y/ N	
Surges	Y/ N	Y/ N	Y/N	Y/ N	
Down to nothing	Y /N	Y /N	Y/N	Y /N	
Gas or Oil	Y/ N	Y/ N	Y/N	Y/ N	
Water	Y/ N	Y/ N	Y/N	Y/ N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks: INJECTING AT THIS TIME ___ WTR, ___ GAS, ___ CO2

Signature: 	OIL CONSERVATION DIVISION
Printed name: Martha Rodriguez	Entered into RBDMS
Title: FSA	Re-test 
E-mail Address: mrbf@chevron.com	
Date: 3-13-18	Phone: 432 254 4167
Witness: Nancy Peterson	