

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

OCT 02 2018

RECEIVED

BRADENHEAD TEST REPORT

Operator Name OCCIDENTAL PERMIAN, LTD	API Number 30-025-05436
Property Name NORTH HOBBS (G/SA) UNIT	Well No. 241

7. Surface Location

UL - Lot - N	Section 13	Township 18-S	Range 37-e	Feet from 660	N/S Line SOUTH	Feet From 1980	E/W Line WEST	County LEA
-----------------	---------------	------------------	---------------	------------------	-------------------	-------------------	------------------	---------------

Well Status

Well Status -	SHUT-IN NO	PRODUCING INT	DATE 9/5/18
------------------	---------------	------------------	----------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csg	(E)Tubing
Pressure	0	0	N/A	57	1026
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	
Steady Flow	Y/N	Y/N	Y/N	Y/N	
Surges	Y/N	Y/N	Y/N	Y/N	
Down to nothing	Y/N	Y/N	Y/N	Y/N	
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks: INJECTING AT THIS TIME ☒ WTR, ☐ GAS, ☐ CO2
4403 Rate

(A) had a puff of gas down to 0
(B) had a puff of gas down to 0

Bryan Colpin
575-441-9739
Bryant

Signature: <u>Mendy Johnson</u>	OIL CONSERVATION DIVISION
Printed name: MENDY JOHNSON	Entered into RBDMS
Title: ADMINISTRATIVE ASSOCIATE	Re-test <u>[Signature]</u>
E-mail Address: <u>mendy_johnson@oxy.com</u>	
Date: <u>SEP 26 2018</u>	Phone: 806-592-6280
Witness:	