

OCT 03 2018

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name OCCIDENTAL PERMIAN, LTD	API Number 30-025-28305
Property Name SOUTH HOBBS (G/SA) UNIT	Well No. COOP 2

7. Surface Location

UL - Lot D	Section 4	Township 19-S	Range 38-E	Feet from 645	N/S Line NORTH	Feet From 453	E/W Line WEST	County LEA
---------------	--------------	------------------	---------------	------------------	-------------------	------------------	------------------	---------------

Well Status

Well Status	SHUT-IN	PRODUCING	DATE 16 July 18	Injector
-------------	---------	-----------	--------------------	----------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Casing	(E)Tubing
Pressure	5	N/R	N/R	22	955
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	Y/N
Steady Flow	Y/N	Y/N	Y/N	Y/N	Y/N
Surges	Y/N	Y/N	Y/N	Y/N	Y/N
Down to nothing	Y/N	Y/N	Y/N	Y/N	Y/N
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Y/N
Water	Y/N	Y/N	Y/N	Y/N	Y/N

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

INJECTING AT THIS TIME ☒ WTR, ☐ GAS, ☐ CO2

A) 5 psi - small puff to nothing
B) No Rise -
C) No Rise -
D) 22 psi small puff to nothing
injecting CO2 @ this time

Daniel Colon
575-318-5067

Signature: <u>Mendy Johnson</u>	OIL CONSERVATION DIVISION
Printed name: MENDY JOHNSON	Entered into RBDMS
Title: ADMINISTRATIVE ASSOCIATE	Re-test
E-mail Address: mendy_johnson@oxy.com	
Date:	Phone: 806-592-6280
Witness:	