

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

OCT 22 2018

RECEIVED

BRADENHEAD TEST REPORT

Operator Name OXY	API Number 30-625-37410
Property Name North Hobbs (LG/SA) unit	Well No. 616

7. Surface Location

UL - Lot 2	Section 19	Township 18S	Range 38E	Feet from 1700	N/S Line 5	Feet From 580	E/W Line W	County Lea
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

TA'D WELL YES ☒ NO ☐	SHUT-IN YES ☐ NO ☒	INJECTOR INJ ☐ SWD ☐	PRODUCER ☒ OIL ☐ GAS ☐	DATE 9/14/15
--	--	---	---	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csng	(E)Tubing
Pressure	10	10	N/A	440	500
Flow Characteristics					
Puff	Y / ☒ N	☒ Y / N	Y / N	Y / N	CO2 ☐
Steady Flow	☒ Y / N	☒ Y / N	Y / N	Y / N	WTR ☐
Surges	Y / ☒ N	Y / ☒ N	Y / N	Y / N	GAS ☐
Down to nothing	☒ Y / N	☒ Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / ☒ N	Y / ☒ N	Y / N	Y / N	Injected for
Water	Y / ☒ N	Y / ☒ N	Y / N	Y / N	Waterflood if
					applies.

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

**1 sec
Blowdown**
needs warning signs

**3 sec
Blowdown**

Danny lane 575-318-1959 DL

Signature: Mendy Johnson	OIL CONSERVATION DIVISION
Printed name: MENDY JOHNSON	Entered into RBDMS
Title: ADMIN. ASSOCIATE	Re-test [Signature]
E-mail Address: MENDY-JOHNSON@OXY.COM	
Date: 10/15/18	
Phone: 806-592-6280	
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM