

HOBBS OCD

APR 24 2019

State of New Mexico
 Energy, Minerals and Natural Resources Department
 Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

RECEIVED

Operator Name Chevron Midcontinent, LP		API Number 30-025-25820
Property Name Central Vacuum Unit		Well No 107

Surface Location

CL - Lot 6	Section 6	Township 18S	Range 35E	Feet from 2450	N/S Line N	Feet from 2632	E/W Line E	County Lea
---------------	--------------	-----------------	--------------	-------------------	---------------	-------------------	---------------	---------------


Well Status

TA'D Well YES	SHUT-IN YES	INJECTOR INJ	PRODUCER OIL	DATE 3/19/19
------------------	----------------	-----------------	-----------------	-----------------

OBSERVED DATA

	(A)Surf-Intern	(B)Intern(1)	(C)Intern(2)	(D)Prod Casing	(E)Tubing
Pressure	0	0		0	1567
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 _____
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR _____
Surges	Y/N	Y/N	Y/N	Y/N	GAS _____
Down to nothing	Y/N	Y/N	Y/N	Y/N	If applicable type
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Fluid injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: 		OIL CONSERVATION DIVISION	
Printed name:		Entered into RBDMS	
Title:		Re-test	
E-mail Address:			
Date:	Phone:		
Witness: Gary Johnson			