

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Chevron Midcontinent, LP		API Number 30-025-32007
Property Name New Mexico L State		Well No 013

Surface Location									
UL - Lot G	Section 1	Township 18S	Range 34E		Feet from 1780	N/S Line N	Feet from 1980	E/W Line E	County Lea

Well Status								
TA'D Well YES	☒ NO	SHUT-IN YES	☒ NO	INJECTOR INJ	PRODUCER SWD	☒ OIL	GAS	D.V.T. 4/14/19

OBSERVED DATA

	(A)Surf-Interm	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	0	NA	NA	20	50
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	If applicable type
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Fluid injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature:		OIL CONSERVATION DIVISION	
Printed name:		Entered into RBDMS	
Title:		Re-test	
E-mail Address:		712	
Date:	Phone:		
Witness:			