

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Chevron Midcontinent, LP		API Number 30-025-32008
Property Name New Mexico L State		Well No 014

2. Surface Location

U/L - Lot B	Section 1	Township 18 S	Range 34 E	Feet from 810	N/S Line N	Feet From 1980	E/W Line E	County Lea
----------------	--------------	------------------	---------------	------------------	---------------	-------------------	---------------	---------------



Well Status

TA'D Well YES	☒ NO	SURF-IN YES	☒ NO	INJECTOR INJ	SWD	PRODUCER ☒ OIL	GAS	DATE 4/14/19
------------------	-------------------------------------	----------------	-------------------------------------	-----------------	-----	--	-----	-----------------

OBSERVED DATA

	(A)Surf-Interm	(B)Interm(1)	(C)Interm(2)	(D)Prod C sug	(E)Tubing
Pressure	0	NA	NA	20	140
Flow Characteristics					
Puff	☒ Y / N	☒ Y / N	☒ Y / N	☒ Y / N	CO2 _____
Steady Flow	☒ Y / N	☒ Y / N	☒ Y / N	☒ Y / N	WTR _____
Surges	☒ Y / N	☒ Y / N	☒ Y / N	☒ Y / N	GAS _____
Down to nothing	☒ Y / N	☒ Y / N	☒ Y / N	☒ Y / N	If applicable type
Gas or Oil	☒ Y / N	☒ Y / N	☒ Y / N	☒ Y / N	fluid injected for
Water	☒ Y / N	☒ Y / N	☒ Y / N	☒ Y / N	Waterflood

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: 		OIL CONSERVATION DIVISION
Printed name		Entered into RBDMS
Title:		Re-test 
E-mail Address:		
Date:	Phone:	
	Witness	