

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Chevron Midcontinent, LP		API Number 30-025-32016
Property Name New Mexico M State		Well No 009

Surface Location

U. - Lot C	Section 1	Township 18S	Range 34E	Feet from 660	N/S Line N	Feet From 2310	E/W Line W	County Lea
---------------	--------------	-----------------	--------------	------------------	---------------	-------------------	---------------	---------------

Well Status

TA'D Well YES	SHUT-IN YES	INJECTOR INJ	PRODUCER GAS	DATE 4/14/19
------------------	----------------	-----------------	-----------------	-----------------

OBSERVED DATA

	(A) Surf-Interm	(B) Interm(1)	(C) Interm(2)	(D) Prod Casing	(E) Tubing
Pressure	0	NA	NA	30	400
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	If applicable type
Gas or Oil	Y/N	Y/N	Y/N	Y/N	fluid injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature:		OIL CONSERVATION DIVISION	
Printed name		Entered into RBDMS	
Title:		Re-test	
E-mail Address			
Date:	Phone:		
	Witness		