

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Chevron Midcontinent, LP	API Number 30-025-32018
Property Name New Mexico R State NCT-1	Well No 014

Surface Location									
UL - Lat	Section	Township	Range		Feet from	N/S Line	Feet from	E/W Line	County
B	6	18S	35 E		860	N	2000	E	LCA

Well Status						DATE
TA'D Well YES ☐ NO ☒	SHUT-IN YES ☐ NO ☒	INJECTOR INJ ☐ SWD ☐	PRODUCER OIL ☒ GAS ☐	4/14/19		

OBSERVED DATA

	(A)Surf Interm	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	3	NA	NA	300	100
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 _____
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR _____
Surges	Y/N	Y/N	Y/N	Y/N	GAS _____
Down to nothing	Y/N	Y/N	Y/N	Y/N	If applicable type _____
Gas or Oil	Y/N	Y/N	Y/N	Y/N	fluid injected for _____
Water	Y/N	Y/N	Y/N	Y/N	Waterflood _____

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature:		OIL CONSERVATION DIVISION	
Printed name		Entered into RBDMS	
Title:		Re-test	
E-mail Address			
Date:	Phone:		
Witness			