

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD
MAY 22 2019
RECEIVED

BRADENHEAD TEST REPORT

Operator Name OCCIDENTAL PERMIAN, LTD		API Number 30-025-43073-0000
Property Name NORTH HOBBS G/SA UNIT		Well No. 680

7. Surface Location

UL - Lot H	Section 24	Township 18-S	Range 37-E	Feet from 2161	N/S Line N	Feet From 537	E/W Line E	County LEA
----------------------	----------------------	-------------------------	----------------------	--------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

TA'D Well YES	SHUT-IN NO	INJECTOR INJ	PRODUCER OIL	DATE 7/16/18
-------------------------	----------------------	------------------------	------------------------	------------------------

OBSERVED DATA

	(A)Surf-Interm	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0			0	0
Flow Characteristics					NOT INS
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	If applicable type
Gas or Oil	Y/N	Y/N	Y/N	Y/N	fluid injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood


Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

POST WORKOVER TEST

PKR 94322
Freddy PDS Rev writ ser# DCM 99
cal 6-22-18

Signature:		OIL CONSERVATION DIVISION
Printed name:		Entered into RBDMS
Title:		Re-test
E-mail Address:		
Date: 7/16/18	Phone:	
Witness: KERRY FORTNER-OCD 575-399-3221		

Wellbore Diagram : NHSAU 680-24



HOBS OCD
MAY 22 2019
RECEIVED

