

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD
JUN 03 2020
RECEIVED

BRADENHEAD TEST REPORT

Operator Name Crosstimbers Energy LLC	API Number 3002523646
Property Name North Vacuum Abo unit	Well No. 146

7. Surface Location

UL - Lot B	Section 14	Township 17S	Range 34E	Feet from 534	N/S Line ENL	Feet From 2134	E/W Line FEL	County LRA
----------------------	----------------------	------------------------	---------------------	-------------------------	------------------------	--------------------------	------------------------	----------------------

Well Status

TA'D Well (YES) NO	SHUT-IN (YES) NO	INJECTOR INJ SWD	PRODUCER OIL GAS	DATE 5-18-2020
------------------------------	----------------------------	---------------------	---------------------	--------------------------

OBSERVED DATA

	(A)Surf-Interm	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	N/A	NA	0	0
Flow Characteristics					
Pull	Y/(N)	Y/N	Y/N	Y/(N)	CO2 _____
Steady Flow	Y/(N)	Y/N	Y/N	Y/(N)	WTR. _____
Surges	Y/(N)	Y/N	Y/N	Y/(N)	GAS _____
Down to nothing	(Y) N	Y/N	Y/N	(Y) N	If applicable type
Gas or Oil	Y/(N)	Y/N	Y/N	Y/(N)	fluid injected for
Water	Y/(N)	Y/N	Y/N	Y/(N)	Waterflood

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFOR	BLACK
-------	-------	-------	--------	-------

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Jacob Bapza	OIL CONSERVATION DIVISION
Printed name: Jacob Bapza	Entered into RBDMS
Title: Production Foreman	Re-test
E-mail Address:	
Date: 5-18-2020	Phone: 575-513-8134
Witness:	

