

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OCD-HOBBS

FORM APPROVED
OMB No. 1004-0135
Expires January 31, 2004

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or re enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well

☐

Oil Well

☐

Gas Well

☒

Other P&A

2. Name of Operator

Yates Petroleum Corporation

3a. Address

105 S. 4th Str., Artesia, NM 88210

3b. Phone No. (include area code)

505-748-1471

4. Location of Well (Footage, Sec., T., R., M., OR Survey Description)

660'FNL & 1980'FWL of Section 28-T23S-R32E (Unit C, NENW)

5. Lease Serial No.

NM-77063

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.

Continental APJ Federal #1

9. API Well No.

30-025-20428

10. Field and Pool, or Exploratory Area

Sand Dunes; Bone Spring, South

11. County or Parish, State

Lea County, New Mexico

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input checked="" type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof.

If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

- 9/5/06 Tubing would not move. Tagged at 4493'. Pumped 60 bbls fresh water. Tubing did not move. Pumped another 60 bbls fresh water and waited 1 hr. Pipe still stuck. Pumped another 40 bbls fresh water while waiting on rotary wireline. Rotary ran freepoint at 4400'. Back off 2-7/8" at 4400'. Fred Wright (BLM) Ok'd to back off.
- 9/6/06 Finished POOH with 66 stands tubing. Washed down to 4413'. Made 6" in 3-1/2 hrs.
- 9/8/06 RIH with 69 stands to 4375'. Screw onto tubing. RIH with 1-7/16" to 8700'. Tubing open to bottom. Pumped 40 sx plug and displace to bottom of tubing. Unscrew tubing and circulated 100 bbls brine.
- 9/11/06 Screw into fish. Pressure up to 700 psi. Tagged at 8830'. Perforated at 6550' and spotted 30 sx cement. WOC. Tagged at 6430'. Perforated at 4650'.
- 9/12/06 Spotted 40 sx cement plug at 4650'. WOC. Tagged at 4380'. Spotted 25 sx cement. WOC. Tagged at 4210'.
- 9/13/06 Circulated plugging mud. Pump mud to clear tubing. Cut 8-5/8" to see if slips were stuck. Pumped 30 bbls fresh water down backside. Perforated at 1257' and pumped 30 sx cement.
- 9/14/06 Tagged at 1008'. Perforated at 395' and pumped 40 sx cement. WOC. Tagged at 200'. Perforated at 100' and pumped 35 sx cement.
- 9/15/06 Installed dry hole marker. Cleaned location. **WELL IS PLUGGED AND ABANDONED. FINAL REPORT.** Please notify Jim Krogman (505-365-8340) 3 days prior to BLM inspection, so we have the opportunity to meet with the inspector on location to confirm all reclamation requirements before receiving the notice of written order.

14. I hereby certify that the foregoing is true and correct

Name (Printed/Typed)

Tina Huerta

Title Regulatory Compliance Supervisor

Signature

Tina Huerta

Date

September 29, 2006

ACCEPTED FOR RECORD

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Wesley W. Ingram

Title

OCT 19 2006

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Wesley W. Ingram
WESLEY W. INGRAM
PETROLEUM ENGINEER

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

GWV