District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. office

Form C-144 June 1, 2004 For drilling and production facilities, submit to appropriate NMOCD District Office.

For downstream facilities, submit to Santa Fe

Santa Fe, NM 87505 Pit or Below-Grade Tank Registration or Closure

Is pit or below-grade tank covered by a "general plan"? Yes \(\subseteq \text{No } \subseteq \text{X} \)

Type of action: Registration of a pit	or below-grade tank L Closure of a pit or below-	grade tank 🔼					
Operator: _CHESAPEAKE OPERATING. INCTelephor	ne: 432-687-2992e-mail address: _S	STRICKLIN@CHKENERGY.CO					
Address: P. O. BOX 11050 MIDLAND. TEXAS 79702	-8050						
	0-025-37906 U/L or Qtr/Qtr K	Sec 27 T 23S R 34E					
	Longitude						
Surface Owner: Federal 🛛 State 🗌 Private 🗎 Indian 🗋							
Pit	Below-grade tank						
Type: Drilling X Production Disposal	Volume:bbl Type of fluid:						
Workover Emergency	Construction material: 3223242526						
Lined X Unlined	Double-walled, with leak detection? Yes If	not, explain why not.					
Liner type: Synthetic X Thickness 12 mil Clay		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1					
Pit Volume 12,139 bbl	44.	not, explain why hot.					
		55 W. 100					
Depth to ground water (vertical distance from bottom of pit to seasonal	Less than 50 feet	(20 points)					
high water elevation of ground water.)	50 feet or more, but less than 100 feet	(10 points)					
280'+	100 feet or more	(0 points 0					
	Too leet of more	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \					
Wellhead protection area: (Less than 200 feet from a private domestic	Yes	(20 points)					
water source, or less than 1000 feet from all other water sources.)	No	(0 points) 0					
Distance to surface water: (horizontal distance to all wetlands, playas,							
irrigation canals, ditches, and perennial and ephemeral watercourses.)	Less than 200 feet	(20 points)					
irrigation canais, ditches, and perennal and epitemetal watercourses.	200 feet or more, but less than 1000 feet	(10 points)					
	1000 feet or more	(0 points) 0					
	Ranking Score (Total Points)	0					
Tests to the control of the control							
If this is a pit closure: (1) Attach a diagram of the facility showing the pit							
your are burying in place) onsite 🛛 offsite 🗌 If offsite, name of facility							
remediation start date and end date. (4) Groundwater encountered: No 🛛	Yes If yes, show depth below ground surface	ft. and attach sample results.					
(5) Attach soil sample results and a diagram of sample locations and excava	tions.						
Additional Comments:							
A SIDE DEEP BURIAL TRENCH WAS EXCAVATED NEXT T							
PIT CONTENTS WERE THEN PLACED INTO THE LINED TR							
AND A TOP COVER OF 20 MIL SYNTHETIC LINER WAS SEWED IN PLACE. THREE FEET OF TOP SOIL WAS PLACED ON TOP OF THE LINED TRENCH AND COMPACTED. THE ORIGINAL PIT WAS BACKFILLED WITH CLEAN SOIL, COMPACTED, AND LEVELLED TO							
GRADE. CONFIRMATION SAMPLES WERE TAKEN FROM THE EXCAVATED PIT PRIOR TO BACKFILLING AND ARE ATTACHED. THE PIT							
CLOSURE WAS STARTED ON DECEMBER 14, 2006 AND CO	OMPLETED ON JANUARY 16, 2007.						
I hereby certify that the information above is true and complete to the best	of my knowledge and belief. I further certify tha	nt the above-described pit or below-grade tank					
has been/will be constructed or closed according to NMOCD guideline	es 🔼, a general permit 🔲, or an (attached) alter	native OCD-approved plan .					
- 1/20/07							
Date: 1/20/07 CLIFF BRUNSON, PRESIDENT, BBC INTL							
Printed Name/Title	Signature (Qi4 P R Fo	OR CHESAPEAKE OPERATING, INC					
Timed Name/Time	Signature_	ok eneski ezike of ekkirino, inc					
Your certification and NMOCD approval of this application/closure does in	not relieve the operator of liability should the content	nts of the pit or tank contaminate ground water or					
otherwise endanger public health or the environment. Nor does it relieve to	the operator of its responsibility for compliance wit	h any other federal, state, or local laws and/or					
Approval:	4	, /					
Approval: Printed Name/Title GARY W. WINK STAFFMG	R Signature naw W.I.) and	Date: 1/31/07					





PHONE (505) 393-2326 • 101 E. MARLAND • HOBBS, NM 88240

ANALYTICAL RESULTS FOR BBC INTERNATIONAL, INC. ATTN: CLIFF BRUNSON P.O. BOX 805 HOBBS, NM 88241 FAX TO: (505) 397-0397

Receiving Date: 01/15/07 Reporting Date: 01/15/07 Project Owner: NOT GIVEN

Project Name: KELLER 27 FEDERAL #2

Project Location: EUNICE, NM

Analysis Date: 01/15/07 Sampling Date: 01/12/07 Sample Type: SOIL

Sample Condition: COOL & INTACT

Sample Received By: BC

Analyzed By: AB

METHOD: Standard Methods 4500-Cl'B

NOTE: Analysis performed on a 1:4 w:v aqueous extract.

Chemist

Date

H12034

PLEASE NOTE: Liability and Damages. Cardinal's liability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analyses. All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including, without limitation, business interruptions, loss of use, or loss of profits incurred by client, its substitutions, affiliates or successors arising out of or related to the performance of services hereunder by Cardinal, regardless of whether such claim is based upon any of the above-stated reasons or otherwise.

CHAIN-OF-CUSTODY AND ANALYSIS REQUEST

ARDINAL LABORATORIES, INC.

2111 Beechwood, Abilene, TX 79603 101 East Marland, Hobbs, NM 88240

Page_/_ of _/_

Company Name: BBC International, Inc.	BILL TO				ANALYSIS REQUEST									
			<i>11</i>			-1	71171	1 313	1120	0201				
		P.O. #:							1	Ì		1	-	
Address: P.O. Box 805	·	Company:		-					Ì		1			
City: Hobss State: NmZip: 8		Attn:		1					- 1					
Phone = 397-6388 Fax #: 397-039	7	Address: Ar	7										l	
Project Project Project Owner:		City:											ļ	
Project Name: Keller 27 Federal 42		State: Zip:						İ	}					
Project Location: Eunice, ~~		Phone #:											į	
Sampler Name: Cliff Brus		Fax #:		الوا										
FOR USE COLY	MATRIX	PRESERV. S	MPLING	رنج					Ì		- 1]	
A A A								ĺ						
000	띪			3					1					
G)PAB OR (C)ON # CONTAINERS	WASTEWATER SOIL GRUDE OIL	OTHER: ACID/BASE: ICE / COOL OTHER:		121		İ		İ			- 1	1		
NO NO NO	STE	취임 2						1						
	WASTEWAT SOIL GRUDE OIL SLUDGE	E IS IS D	TE TIME											
H12034-1 P.+ Bothon G1		1 19/1	107 12:30	, –			1							
				-										
							 							
		 		+-+		 	+ - +							
		- - -		 -			├							
							╁┈╌┼				-+			
	+ + + + + + + + + + + + + + + + + + +			 			++							
				\vdash		+-	┼┼							
				 		-				_	-			
PLEUSE HOTE: Linday and Durnayou, Cardona's Subsity and closes successor surrouty for any closing whired	er based in contract or to	ri, shall be broked to the amount	and by the cherk for the				Terr	and Cond	Seices: IN H	(14) H	ther ped to	*******	more for Educa of Shreica,	
Maryunet, Al Cheira I TELETINI, Diolet for recipioniste and any other causes who becomes what he determed whatevel unless Lacroca. In the energy and Continue he both for tracement or consequental outsigner, including without fritindon, bus	hoes hacraptions, less of	luse, or lose of predice incurred b	diers, he subeldierios,	icable			and a	ye pase our Coords of or	obectors, h	raludro Milo	arey's loss	*.		
Sampler Relinguished: Date: / Received		seed upon any of the shows state	Phone Re	sult:	□Yes	□No	A l'bbA	hone #						
1/15/07			Fax Resu	lt:	□ Yes	□ №	Add'l F	ax #:						
Can Jun 11:55-am			REMARK	S:										
Relinquished By: Date: Received	By: (Lab Staf	f)												
Time: //,	11601	10/11												
150	Sample Condition	ON CHECKED B												
	Cool Intaint	(elsitini)												
Sampler - UPS - Bus - Other:	NO NO									,,,,, <u>,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,</u>				

[†] Cardinal cannot accept yerbal changes. Please fax written changes to 505-393-2476.