District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

Printed Name/Title L JOHNSON - ENVIRO ENGR

### State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-144 March 12, 2004

For drilling and production facilities, submit to appropriate NMOCD District Office.
For downstream facilities, submit to Santa Fe office.

Samples are to be obtained from pit floor area in each quadrant and analysis submitted to NMOCD prior to back-filling. (Chloride)

## Pit or Below-Grade Tank Registration or Closure

Is pit or below-grade tank covered by a "general plan"? Yes 🛛 No 🗌 Type of action: Registration of a pit or below-grade tank \(\subseteq\) Closure of a pit or below-grade tank \(\subseteq\) **Operator: Marbob Energy Corporation** Telephone: 505-748-3303 e-mail address: land2@marbob.com Address: PO Box 227, Artesia, NM 88211-0227 1980' FNL & 1980' FWL Facility or well name: Scooch State Com #1 API#: 30-025-36995 U/L or Otr/Otr SENW Sec 23 T 18S R 33E County: Lea NAD: 1927 ☐ 1983 ☐ Surface Owner Federal ☐ State ☒ Private ☐ Indian ☐ Pit Below-grade tank Type: Drilling ☑ Production ☐ Disposal ☐ bbl Type of fluid: Volume: Workover Emergency Construction material: Lined Unlined Double-walled, with leak detection? Yes If not, explain why Liner type: Synthetic 

☐ Thickness 12 mil Clay ☐ Volume (20 points Less than 50 feet Depth to ground water (vertical distance from bottom of pit to seasonal high (10 points) 50 feet or more, but less than 100 feet water elevation of ground water.) 100 feet or more Yes (20 points) Wellhead protection area: (Less than 200 feet from a private domestic No ( 0 points) 0 points water source, or less than 1000 feet from all other water sources.) Less than 200 feet (20 points) Distance to surface water: (horizontal distance to all wetlands, playas, 200 feet or more, but less than 1000 feet (10 points) irrigation canals, ditches, and perennial and ephemeral watercourses.) 1000 feet or more ( 0 points) 0 points Ranking Score (Total Points) 0 points If this is a pit closure: (1) attach a diagram of the facility showing the pit's relationship to other equipment and tanks. (2) Indicate disposal location: onsite offsite If offsite, name of facility Sundance Disposal. (3) Attach a general description of remedial action taken including remediation start date and end date. (4) Groundwater encountered: No 🛛 Yes 🔲 If yes, show depth below ground surface ft. and attach sample results. (5) Attach soil sample results and a diagram of sample locations and excavations. \*Drilled 65' test hole at 865' FNL & 1650' FWL Sec 23-T18S-R33E. No water encountered. INFO INCONCLUSIVE DUE TO PROCEDURE I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that the above-described pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit. An of an (attached) alternative OCD-approved plan. Date: June 6, 2007 **Gerald Herrera** Printed Name/Title: Signature Your certification and NMOCD approval of this application/closure does not relieve the operator of liability should the contents of the pit or tank contaminate ground water or otherwise endanger public health or the environment. Nor does it relieve the operator of its responsibility for compliance with any other federal, state, or local laws and/or regulations.

# Marbob Energy Corporation Attachment to OCD Form C-144


### Pit or Below-Grade Tank Registration or Closure

Pit Closure

#### Scooch State Com #1

1980' FNL & 1980' FWL Section 23 T-18S R-33E Lea County, New Mexico

(1) Facility diagram



(2) Disposal location:

Truck and haul cuttings to Sundance Disposal.

- (3) General description of remedial action:
  - a. Use caliche from road and pad to fill pit.
  - b. Use stock piled dirt to cover pit, reseed per landowner's specifications.
- (4) Groundwater encountered:

No

 Drilled an 80' test hole on the Rhoid State #1 well at 330' FNL & 330' FWL Section 24 T-18S R-33E - Water leached into hole to 62'.
 Well Record submitted previously

(5) Soil sample: SAMTLE PITHER CHLOREDE - CLIAN TO 250 FPM

NATURAL SABRITE SAMPLE DATA OF CLOSURE