

**RECEIVED**

JUN 10 2009

**HOBBSOCD**

Submit 2 Copies To Appropriate District Office

State of New Mexico  
Energy, Minerals and Natural ResourcesForm C-103  
October 25, 2007District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Ave., Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505WELL API NO. /  
30-025-064865. Indicate Type of Lease  
STATE ☒ FEE

6. State Oil &amp; Gas Lease No.

7. Lease Name or Unit Agreement Name  
Northeast Drinkard Unit

8. Well Number 219 /

9. OGRID Number  
00087310. Pool name or Wildcat  
Eunice Blinbry-Tubb-Drinkard, North

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: ☒ Oil Well ☐ Gas Well Other Injection2. Name of Operator  
Apache Corporation3. Address of Operator  
6120 South Yale Avenue, Ste. 1500, Tulsa Oklahoma 74136-4224

## 4. Well Location

Unit Letter: N : 3550' feet from the S line and 2300' feet from the W lineSection 2 Township 21-S Range 37-E NMPM Lea County 

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

## 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

## NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐OTHER: ☐

## SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐☒ Location is ready for OCD inspection after P&A

- x All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.
- x Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.
- x A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the

**OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. ALL INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.**

- x The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.
- x Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.
- x If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location.
- x All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)
- x All other environmental concerns have been addressed as per OCD rules.
- x Pipelines and flow lines have been abandoned in accordance with 19.15.9.714.B(4)(b) NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.

When all work has been completed, return this form to the appropriate District office to schedule an inspection. If more than one inspection has to be made to a P&A location because it does not meet the criteria above, a penalty may be assessed.

SIGNATURE Guinn Burks TITLE Remediation Foreman DATE 6-8-09TYPE OR PRINT NAME Guinn Burks E-MAIL: guinn.burks@apachecorp.com PHONE: 432-683-6511

For State Use Only

APPROVED BY: Mark Whitaker TITLE Comp. Officer DATE 06-18-09

Conditions of Approval (if any):