

Submit 1 Copy To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
October 13, 2009

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. <b>30-025-25556</b> ✓
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/> ✓
2. Name of Operator <b>VPR Operating, LLC</b> ✓		6. State Oil & Gas Lease No.
3. Address of Operator <b>1406 Camp Craft Rd. Ste. 106, Austin, Tx 78746</b>		7. Lease Name or Unit Agreement Name <b>SFRR</b> ✓
4. Well Location Unit Letter <b>K</b> : <b>1798</b> feet from the <b>South</b> line and <b>2062</b> feet from the <b>West</b> line Section <b>33</b> Township <b>9S</b> Range <b>37E</b> NMPM County <b>Lea</b> ✓		8. Well Number <b>23</b> /
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. OGRID Number <b>266091</b> ✓
		10. Pool name or Wildcat <b>West Sanger; San Andres</b> ✓

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☒  
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

12.15.2010 - 12.20.2010 RLI workover unit. Rods & tbg stuck - on an attempt to pull rods, Rods parted below PR. Unflange well head. Attempt to pull tbg - tbg stuck. Attempt to fish rods - no success. Finally successful in getting rods to manually back off. LD 40 7/8" rods. POKED 3 ft of 2 3/8" tbg. Rods & tbg scaled up 100'. TTH of tbg - screwed on - attempts for an outside back off failed. Screwed back into rods. Unable to fish. RU J & B, steel pit. water tank. After approval turn OCD, pump 25 sx. cement plug @ 1332' WOC. Tagged @ 873'. RLI Retortary W2. Perforate 4 holes @ 450'. Pumped 40 SXS. Can't C. Couldn't pump into squeeze hole. Fill up to surface. Cut off well head. Installed DH Cap. Cut off anchor. Clean loc. Ready for OCD release.

Spud Date:

Rig Release Date:

Job witnessed by  
Maxey Brown.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE Agent DATE 1/8/2011  
Type or print name M. Y. Merchant E-mail address: mymerch@hotmail.com PHONE: (575) 492-1236  
For State Use Only  
APPROVED BY [Signature] TITLE STAFF DATE 1-10-2011  
Conditions of Approval (if any):

Approved for plugging of well bore only.  
Liability under bond is retained pending receipt  
of C-103 (Subsequent Report of Well Plugging)  
which may be found at OCD Web Page under  
Forms: [www.emnrd.state.nm.us/oed](http://www.emnrd.state.nm.us/oed).