

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. 30-025-03603

5. Indicate Type of Lease
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL ☒ WELL ☐ GAS ☐ WELL ☐ OTHER Swd

2. Name of Operator
Bordeaux Petroleum Company

3. Address of Operator
333 W. Hampden Ave. Suite 604, Englewood, Co 80110

4. Well Location
Unit Letter M : 660 Feet From The South Line and 660 Feet From The West Line

Section 26 Township 9S Range 36E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
4030 D.F.

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Started back on Injection ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

On 2/13/90 - Clean up acidized well 1/10,000 gals - 15% HCL-Avg Pump Rate 3.8 BPM @ 50 psig. Max. press. 50 psi, Final 30 psi, ISOP-on vac. Flushed Acid with Produced water rig up Pressure Chart on Annulus and Pressure tested Annulus to 500 psi held for 30 min. The State Field inspector who witnessed the Mechanical integrity test. Tubing Pressure was 35 psi and Csg Annulus Pressure @0psi. Added a drum of packer Fluid w/fresh water down the back side and pressured up to 500 psi and Shut in Valve on Annulus, Place well back into SW Disposal System.

See Attached.

well diagram.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Bruce M. Patterson TITLE Vice President-Engineering & Operations DATE _____

TYPE OR PRINT NAME Bruce M. Patterson

TELEPHONE NO. 303-761-3707

(This space for State ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE JUL 6 2 1990

CONDITIONS OF APPROVAL, IF ANY: