radioactive tracer/temperature log that is required to be conducted on this well pursuant to the terms of Order No. SWD-662. In addition, what is this well's current status with regards to mechanical integrity; and

Ĵ

 d) with regards to the Crossroads Siluro Devonian Unit No. 104, located in Unit O of Section 34, T-9 South, R-34 East, NMPM, and which was originally permitted as a disposal well by Division Order No. R-3612, what is the current status with regards to this well's mechanical integrity.

In addition, are there any other violations that I should be aware of concerning these four proposed injection wells? I appreciate your time and effort to provide me with this important information.

Sincerely, mid atquart

David Catanach Examiner

Xc: Mr. William F. Carr Case File--12418 Mr. David Brooks Mr. Richard Ezeanyim