



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYLand Office Santa Fe.
Lease No. LC 065219
Unit 11 11 21

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	
<u>Well Completion</u> X	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

November 16, 1959

Federal "D"

Well No. 1 is located 660 ft. from [N] line and 660 ft. from [E] line of sec. 31SE/4, SE/4 (1/4 Sec. and Sec. No.) 9-S (Twp.) 36-2 (Range) NTP (Meridian)Wildcat (Field) Lea (County or Subdivision) New Mexico (State or Territory)The elevation of the Ground ~~bottom floor~~ above sea level is 4053 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Total Depth 12,031'.Ran 4092' of 8-5/8" OD casing, cemented with 1391 sacks. Ran 12,030' of 5-1/2" OD casing and cemented with 260 sacks. Perforated 5-1/2" casing 12,003'-12,023' with 4 jet shots per foot. Treated perfs with 500 gallon mud acid.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company The Pure Oil CompanyAddress Box 671Midland, TexasBy W. A. TownsendTitle Chief Clerk