

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1006)

Name of Company Cabeen Exploration Corporation				Address 211 North Ervay Bldg., Dallas 1, Texas			
Lease Union State	Well No. 1	Unit Letter L	Section 10	Township 10	Range 36		
Date Work Performed 5-18-62 to 5-31-62		Pool		County Lea			

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations
 ☐ Casing Test and Cement Job
 ☐ Other (Explain):
- ☒ Plugging
 ☐ Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

1. Spotted 40 sx. cement plug to cover perforations.
2. Loaded hole with mud laden fluid.
3. Shot and recovered 6050' of 5-1/2" casing.
4. Spotted 25 sx. cement plug at stub of 5-1/2" casing.
5. Spotted 25 sx. plug at 5500'.
6. Spotted 25 sx. plug at 4150'.
7. Spotted 25 sx. plug at stub of 8-5/8" casing, 1150' recovered.
8. Spotted 25 sx. plug at 330', base of 13-3/8" casing.
9. Spotted 10 sx. plug at top of well and erected a 4" marker.

Witnessed by Stanley Saikin	Position Superintendent	Company Hobbs Pipe and Supply
---------------------------------------	-----------------------------------	---

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA

D F Elev.	T D	P BTD	Producing Interval	Completion Date
Tubing Diameter	Tubing Depth	Oil String Diameter	Oil String Depth	
Perforated Interval(s)				
Open Hole Interval		Producing Formation(s)		

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

OIL CONSERVATION COMMISSION		I hereby certify that the information given above is true and complete to the best of my knowledge.	
Approved by <i>Leshie A. Clements</i>	Name <i>Stanley Saikin</i>	Position Superintendent	
Title	Company Hobbs Pipe and Supply		
Date			